



03/29/13

## FTDX3000 Software Update and Version Identification

The latest versions are listed below with the release dates.

- MAIN Software Version **0112** (3/29/13)
- TFT Software Version **0106** (01/09/13)

\*If you already have **MAIN: V0112** and **TFT: V0106** software versions, it is not necessary to update the FTDX3000 again.

There are four different Software installations. Each one must be followed carefully. Installing the wrong type software may cause difficulties. Check your radio before installing software to be sure which updates are needed.


If multiple software installations are required the **MAIN** software should be installed first, as it is the only one that requires a press and hold in the [FAST] and [LOCK] keys while turning the radio back on. This resets the radio and locks in the new software.

Before installing new firmware, please verify your current version firmware with the following procedure:

### How to Confirm the Firmware Version

Press and hold the [POWER] key to turn on the transceiver, while pressing and holding the [SCOPE] key, [GEN] key, [50] key, and [ENT] key on the transceiver's main panel.

The versions of each firmware will be displayed on the TFT screen.



(This image & version is for illustration only)

Download the FTDX3000 data and [**FTDX3000\_MAIN (V0112) and TFT (V0106).zip**] from the following website:

<http://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=721B3F7D596827E0B37BD528EE1A56F1&DivisionID=65&isArchived=0>

**Please read the FTDX3000 Firmware Upgrade Manual before proceeding!**

**Ver. 0112 MAIN CPU** (03/29/13)

- If the MAIN VFO (A) is locked, in split operation when the [TXW] button is held, the Sub VFO will lock when the [TXW] button is released, and the Sub VFO will be unlocked.
- When the  $\mu$ TUNE unit is not connected, if you push and hold the [MHz/ $\mu$ T] button; the reception signal path is through the  $\mu$ TUNE IN/OUT terminals (In this condition you can connect band pass filters outside of the radio).
- Additional functions are improved and optimized.

**Ver. 0106 TFT** (01/09/13)

- Correct minor bug and implement improvements

We hope this new firmware will increase your enjoyment of your FTDX3000. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu, Amateur Tech Support [amateurtech@yaesu.com](mailto:amateurtech@yaesu.com).

Best regards,

**Mikio Maruya, WA6F**  
Executive Vice President  
Engineering & Customer Service  
Yaesu USA