



07/14/15

FTDX3000 Software Update and Version Identification

The latest versions are listed below with the release dates.

- DSP Software Version **05-54** (07/14/15)
- MAIN Software Version **01-20** (07/14/15)
- TFT Software Version **01-09** (07/14/15)

*If you already have EDSP: Ver. **05-54**, MAIN: Ver. **01-20** and TFT: Ver. **01-09** software versions, it is not necessary to update the FTDX3000 again.


There are four different Software installations. Each one must be followed carefully. Installing the wrong type software may cause difficulties. Check your radio before installing software to be sure which updates are needed.

If multiple software installations are required the **MAIN** software should be installed first, as it is the only one that requires a press and hold in the [FAST] and [LOCK] keys while turning the radio back on. This resets the radio and locks in the new software.

Before installing new firmware, please verify your current version firmware with the following procedure:

How to Confirm the Firmware Version

Press and hold the [POWER] key to turn on the transceiver, while pressing and holding the [SCOPE] key, [GEN] key, [50] key, and [ENT] key on the transceiver's main panel. The versions of each firmware will be displayed on the TFT screen.



(This image & version is for illustration only)

Download the FTDX3000 data and [**FTDX3000_Update_JULY14.zip**] from the following website:
<http://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=721B3F7D596827E0B37BD528EE1A56F1&DivisionID=65&isArchived=0>

Please read the FTDX3000 Firmware Upgrade Manual before proceeding!

Main: Ver. 1.20 (07/14/15)

TFT: Ver. 1.09 (07/14/15)

- Waterfall displays 25 Seconds worth of Historical Spectrum Data.
- The Waterfall or Waterfall-scope (Combination) can now be displayed in Full Screen.
- The Spectrum scope and AF-FFT scope will now display concurrently with the Water Fall.
- The Spectrum Scope Memory function can store spectrum data and shows signal data within the water fall display by pressing and holding the “Select” key for one second.

DSP Ver. 0554 (7/14/15)

- Improved and optimized.

The zip file contains all of the current software versions. Please verify which version software is already on your radio before updating. If you have each of the listed versions, you do not need to update the radio again.

We hope this new firmware will increase your enjoyment of your FTDX3000. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu, Amateur Tech Support amateurtech@yaesu.com.

Best regards,

Mikio Maruya, WA6F
Executive Vice President
Engineering & Customer Service
Yaesu USA